

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 12078

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080118-3

RECEIVED FROM

G. V. Controls

DATE REC'D. 5-3-57

P.O. NO.

VENDOR PACKING SLIP NO. 633

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY		REMARKS
									ACCEPTED	REJECTED	
	322	000000	NO-1								
10		730125-13	Relay Time Delay 5 Sec. C-7							10	H. S. Lott
			-04 NC-28 (32-000000-25-0-23)								
10		730125-26	Relay Time Delay 3 sec. (-V RFF							10	" "
			-01 NC-28 (32-000000-106-0-23)								

Transp. Rec. Insp. Report #17097  
dated 5-2-57

RECEIVED  
BY HMC-1009INSPECTED  
BY

DATE

REJECTS RETURNED  
ON SHIP. MEMO NO.

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 12089

RECEIVED FROM

2541 E. COLORADO ST., PASADENA CALIF.

PLATE #9

DATE REC'D. 5-6-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	QUANTITY		REMARKS
									ACCEPTED	REJECTED	
4	322	000000	10	0	20					4	H. S. Lott
		738260	Leaving bracket Assembly								
			IPS #2307								
			Ref: Stores Req: 71610								

(Transp. Rec. Insp. Report #17097)

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080118-3

RECEIVED  
BY HMC-1009INSPECTED  
BY

DATE

REJECTS RETURNED  
ON SHIP. MEMO NO.